# INDUSTRIAL ENGINEER

## INDEX TO VOLUME 81

*January to December*, 1923

E. In El
En621.5
f In206

### GENERAL INDEX

Pages by Months


| | |
|---|---|
| January | 1 to 68 |
| February | 69 to 120 |
| March | 121 to 172 |
| April | 173 to 226 |
| May | 227 to 278 |
| June | 279 to 326 |
| July | 327 to 374 |
| August | 375 to 422 |
| September | 423 to 470 |
| October | 471 to 518 |
| November | 519 to 566 |
| December | 567 to 614 |



## A

Accident prevention (see Safety).
Accounting.
——Maintenance work, procedure in (Arthur J. Whitcomb), *11, *426.
——Power costs, checking and distributing (Arthur J. Whitcomb), *181, editorial comment, 208.
Alarms (see Signals)
Alternating-current obtained from d.c. machine (Philip G. Bernholz), *413 (R. M. Beecher), *602.
American Sugar Refining Company's works, *520.
Ammeters connected for three-phase, three-wire circuits, *507.
Anchor bolts, stove bolts and pieces of lead pipe used for (E. R. Howard), *214.
Answers to readers problems (see Questions and Answers).
Arc welding (see Welding).
Armatures:
——Baking (John S. Dean), *165, *367.
——Banding machine made from old lathe (H. R. Wass), *607.
——Dipping (John S. Dean), *165, *367.
——Growler for testing, *505.
——Handling, iron band as sling for (Frederick Krug), *366.
——Insulation, 408.
——Winding:
Devices for, small (H. E. Ewalt), *113.
Direct-current, data for old (A. C. Roe), *98.
Rack made from pipe and fittings (John W. Hobart), *418.
Association of Iron & Steel Electrical Engineers:
——Convention program, *454.
——Convention, report of, *474, editorial comments, 502, 503.
Auditing procedure in maintenance work (Arthur J. Whitcomb), *11, *426.

## B

Baldwin Locomotive Works, *424.
Batteries, charging storage, *507.
Bearings:
——A. I. S. E. E. special bearing committee, report of (D. M. Petty), 477.
——Oil leaks in (Frederick Krug), 605.
——Oil not simply oil, when is (editorial comment), 549.
——Oiling, care in (Jos. B. Humphrey), 161.
Bells, contact points on, 359.
Belts:
——Additional steps in making endless leather (Louis W. Arny), *413.
——Fabric-base and leather (Frank E. Gooding), *147.
——Joints in, arranging laps of cemented (A. J. Dixon), *362.
——Laps for cemented endless leather, making (Louis W. Arny), *365.
——Leather cement—how to apply it in joining leather (Louis W. Arny), 459.
——Operating conditions affecting, service (Frank E. Gooding), *189, correction, (R. H. Whitney), 324.
——Pulley guard keeps oil which escapes from bearing from saturating (A. J. Dixon), *110.
——Reclaiming leather (Frank E. Gooding), *304, (editorial comment), 311.
——Records in industrial works, keeping belt operation (E. D. F.), *556.
——Servicing industrial (Frank E. Gooding), *236 (editorial comment), 262.
Boilers, electric steam (P. H. Falter), *403, comment, (W. A. Plant), 509, answer (P. H. Falter), 509.
Bolts ajustable, making anchor (Frank Harazim), *458.
Bonus on operation and maintenance (A. A. Frank), *4, correction, 119.
Books, practical:
——Aluminum repairing (Wm. H. H. Platt), 613.
——Belt conveyors and belt elevators (Frederic V. Hetzel), 613.
——Chemical resistance of engineering materials (Marston Lovell Hamlin and Francis Mills Turner, Jr.), 613.
——Control, stores and materials (Madison Cartmell), 613.
——Distribution, economics of electrical (P. O. Reyneau), 613.
——Exposition, technical (Karl Owen Thompson), 223.
——Insulation, plastic and moulded electrical (Emile Hemming), 373.
——Lighting circuits and switches (Terrell Croft), 613.
——Machinery foundations and erection (Terrell Croft), 223.
——Metals and their alloys (Charles Vickers), 373.
Books, practical:
——Transients, electrical (Magnuson, Kahn and Tolmie), 373.
——Troubles in electrical machines, diagnosing of (Miles Walker), 223.
——Welding encyclopedia (Mackenzie and Card), 223.
——Year book, E.M.F. electrical (F. H. Bernhard, editor), 373.
Brushes:
——Position of, on commutator, finding proper (George Wm. Hanlon), *554.
——Repulsion-induction motor, shifted by hand (Henry Mulford), *316.
——Troubles caused by armature and field defects that appear at the (E. H. Martindale), *575.
——Twenty-year service record, with (Practical Pete), *173.
Bulbs, incandescent lamp (see Lamps).

## C

Cables:
——Ampere rating of, figuring, 358.
——Equalizer, size of, 506.
——Hook facilitates overhead installation of, in factory (W. L. Rambousek), *215.
——Lead-covered, where they are necessary in industrial plants (F. A. Westbrook), 215.
——Oil-proof, for printing presses (F. A. Westbrook), *364.
——Rating of, figuring ampere, 264.
Cement, heat-resisting and insulating, 54.
Chain drive:
——Operating conditions affecting, service (Frank E. Gooding), *379.
——Production losses reduced by, in Automatic Electric Company's plant (Frank E. Gooding), *432.
——Types and kinds of (Frank E. Gooding), *335, editorial comment, 357.
Charts (see Records).
Christmas, it's 25 days 'till (Practical Pete), *567.
Circuit breakers for dc. motors (James H. Wyatt), *523.
Clip for emergency connections (G. A. Luers), *461.
Coal (see Handling materials).
Codes:
——Lighting, industrial (G. H. Stickney), *447.
——National Electrical, changes in (E. H. Hubert), *187.
Coils:
——Basket-shape, rewinding motor with, 457.
——Double-nose, winder for (E. T. Walk), *366.
——Exploring, simplify work of tracing conductors (Philip Bernholz), *271.
——Field:
Fixtures to hold, while being taped (J. M. Walsh), *558.
Testing, *159, 210.
——Induction-motor, how to group (A. C. Roe), *137, *197, *241, *293.
——Stator, what's your best record for inserting (Practical Pete), *471.
——Unequal groupings of, laying out (A. C. Roe), *241.
Communication (see Signals).
Commutators:
——Brushes on, finding proper position of (George Wm. Hanlon), *554.
——Defects in (E. H. Martindale), *153.
——Ring-fire (R. Tokea), 162.
Concrete foundation when blasting, wet straw aids removal of (H. C. A.), 602.
Condenser for 110-volt a.c. circuit, small, 55, 107.
Conductors (see Wire and Wiring).
Conduit:
——Grounding, requirements for, *552, 598.
——Hose protects wires in, from water (F. G. F.), *268.
——Turning, in emergency without a pipe wrench (G. F. H.), *316.
Contractor, duties and responsibilities of the electrical (Daniel H. Braymer), *16.
Control, motor (see Motor control).
Conveyors:
——Cases of petroleum products, for *168.
——Coal loaded on trucks by portable belt, *369.
——Coal, reclaiming with portable, *514.
——Hot materials, for handling, 323.
——Scrap, for piling rusty, *64.
——Varnish, for speeding up shipments of, *321.
Copper, preventing corrosion of, 456, 504.
Costs:
——Power, checking and distributing (Arthur J. Whitcomb), *181, editorial comment, 208.
——Pumping water (editorial comment), 548.
——Repair job, of a (editorial comment), 310.
——Repair shop, analyzing electrical (George P. Svendsen), *23.
Cotton mills (see Mills).
Counterweights, inexpensive (G. A. Luers), *508.
Couplings:
——Flexible, for special job (Frederick Krug), *315.
——Flexible, types and kinds of (Frank E. Gooding), *529, editorial comment, 548.
——Flexible, installation and operation of (Frank E. Gooding), * 579.
——Rigid and compression, use of (Frank E. Gooding), *499.
Cranes:
——Collector wires, 106, *359, 410.
——Improvised, to take high-pressure cylinder from large engine (Henry Mulford), *460.
——Pipe, for handling, *117.
——Swinging jib, relieve traveling crane, *275.
——Traveling, operating and maintenance practice for electric (B. Hantman), *176.
——Trolley bar, expansion and contraction of steel, 312.
Cutting cast iron of various thickness by electric arc, speed of (A. M. Candy), *220.

## D

Desk memorandum roll paper, holder for (G. A. Luers) *510.
Diagrams (see Records).
Direct-current:
——A.c. obtained from, machine (Philip G. Bernholz), *413 (R. M. Beecher), *602.
——Control, low-voltage (Paul F. Clausen), *257.
Distribution circuits, grounding, 212.
Drilling holes on surface of large cylinder with magnetic "old man," (W. A. Plant), *512
Du Pont de Nemours and Company's works, E. I., *376.

## E

Editorial comments, 52, 104, 208, 262, 310, 356, 406, 452, 502, 548, 594.
Electric Power Club:
——Motors and generators, recommendations for installation and care of, *540, editorial comment, 548.
——Standards, power apparatus (editorial comment), 595.
——Transformers, recommendations for care and operation of power, *348, editorial comment, 357.
Electrical development committee of A. I. S. E. E., report (Walter C. Kennedy), 474.
Electromagnets (see Magnets).
Elevators, electric:
——Barrels handled by tiering machine, *221.
——Floor level difference overcome by using, instead o ramp, *168.
——Inspection (J. M. Walsh), *72.
Emery-wheel arbor reclaiming a seemingly wornout (A. J. Dixon), *463.
Endicott-Johnson Corporation, works, *568.
Engineer, duties and responsibilities of the consulting (Daniel H. Braymer), *16.
Equipment produced in 1922, new (E. H. Hubert), *89.
Exploring coils simplify work of tracing conductors (Philip G. Bernholz), *271.
Explosion of totally-inclosed motor, 601.

## F

Factor, power (see Power factor).
Fans:
——A. c., burn out when six blades are substituted for four (A. C. Roe), 219.
——Rewinding desk, *411.
Filing (see Records).
Fire loss of electrical origin, decrease in (editorial comment), 357.
Flashlight cells, better service by cleaning contacts o (Henry Mulford), 110.
Flour Mills Company's works, Pillsbury, *122.
Foreman as a teacher, the (editorial comment), 356.
Furnace, electric:
——Phenomena (Edward T. Moore), 483.
——Soldering irons, for heating (A. S. Barker), *464.
Fuses:
——Heating of ferrule-type, in single finger clips (Henry Mulford), 317.
——Motor protection, for (William E. Seward), *85.
——Restoring service quickly after blowing of (Donald L. Hoare), *605.
——Tester made from pocket flashlight (J. E. McCarthy) *219.
——Testing board (Donald L. Hoare), *272.

## G

Gage, moving lamp for reading glass oil (A. J. Dixon), *215.
Gas, lamp for burning out accumulations of explosive (Dr. H. C. P. Weber), *216.
Gas, lightings, by electricity, *160.
Gears:
——Information about (G. A. Van Brunt), *131.
——Use of (G. A. Van Brunt), *81.
Generator repairs:
——Amatures, winding and connecting data for old d.c. (A. C. Roe), *98.
——Equipotential connections, making, 107.
Generators:
——Direct-current:
Alternating-current from, obtaining (Philip G. Bernholz), *413 (R. M. Beecher), *602.
Two, operated in parallel, *598.
——Installation and care of Electric Power Club's recommendations for, *540, editorial comment, 548.
——110- and 220-volt service from 220-volt, securing, *411, *551.
——Plating, what to do and what not to do when it sparks (H. S. Rich), 268.
Gregory Electric Company's plant, details of procedure in repairing and rebuilding electrical equipment (J. D. Zook), *383.
Grounded circuit, trouble from 109, 265.
Grounding:
——Conduit, requirements for, *552, 598.
——Distribution circuits, 212.
Growler for testing armatures, *505.

## H

Handling materials (see also Conveyors, Cranes, Hoists, Magnets, Tractors, Trailers, Trucks, etc.).
——Barrels, heavy, *221.
——Bates Expanded Steel Truss Company's works, in the (G. A. Van Brunt), *345.


*Indicates illustrated articles

330125

FEB 17 '25
ED. 2. Jr. (EN.)

Handling materials:
——Byproducts of better methods for (editorial comment), 503.
——Cases of petroleum products, conveyor for, *168.
——Castings:
Between machines, *561.
To and from annealing furnace, *321.
——Coal:
Drag line for leveling pile made from scraper and tractor (H. S. Rich), *466.
Reclaiming, *369.
Reclaiming, with portable conveyor, *514.
Screenings and coke breeze, *323.
——Cores in steel foundry, 170.
——Cottonseed oil meal, bags of, *370.
——Dies, *116, *465.
——Design of equipment affects, proper, *513.
——Forgings, hot, *275.
——Heavy work lifted and held while fabricating by hoists, *466.
——Hot materials between operations or processes, 323.
——Iron removed from silver ore by magnet, *222.
——Machined parts protected by skids, delicate, *170.
——Machines supplant cheap labor (editorial comment), 453.
——Mail bags, *560.
——Methods of, better (Frank E. Gooding), *41.
——Motor parts, *609.
——Paint-dipping, for *63.
——Paper rolls, *64.
——Pipe, *117.
——Poles, steel (G. A. Van Brunt), *345.
——Scrap, *64, *169.
——Screw machine turnings, loose, *116.
——Signals notify when loads are ready or empty trailers are wanted, 274.
——Steel bars, moving hacksaw to work eliminates double handling of heavy, 63.
——Steel plant yards, third-rail construction for electric transportation (F. O. Schnure), *555.
——Varnish shipments, *321.
——Wire, tramrail hoist for handling bundles of, *222.
Heaters, electric:
——Flat-topped, for contact drying (Albert Kochs), *268.
——Vaporizing water, electrically-heated tank for (Albert Kochs), *415.
Hoists:
——Blast furnace skip (A. C. Cummins and A. R. Leavitt), 484, *513.
——Coal screenings and coke breeze, for handling, *323.
——Heavy work lifted and held while fabricating by, *466.
——One-hand individual, *609.
——Overrunning prevented by stopping motor (W. W. Peasgood), *415.
——Scrap, for handling, *169.
——Second floor used for storage with, 514.
——Tramrail, for handling bundles of wire, *222.

## I

Incandescent lamps (see Lamps).
Industrial Engineer: concerning the kind word (editorial comment), 157.
Industries, our basic American (editorial comment), 209.
Inspection and Maintenance:
——Auditing procedure in maintenance work (Arthur J. Whitcomb), *11, *426.
——Bonus on operation and maintenance (A. A. Frank), *4, correction, 119.
——Bossert Corporation's works, in (E. S. Lincoln), *283.
——Breakdown alibis, the remedy for (editorial comment), 52.
——Brushes, troubles caused by armature and field defects that appear at the (E. H. Martindale), *575.
——Dennison Mfg. Co., in the (H. S. Knowlton), *231.
——Costs are the key to replacements, when (editorial comment), 156.
——Cranes, electric traveling (B. Hantman), *176.
——Elevator, electric (J. M. Walsh), *72.
——Ounce of inspection vs. pound of repair (editorial comment), 52.
——Ladders for, folding, *217.
——Maintenance:
Analyses and procedure (G. A. Van Brunt), *48.
Auditing procedure in (Arthur J. Whitcomb), *11, *426.
Bonus on operation and (A. A. Frank), *4, correction, 119.
Charges for, how to figure (G. W. Bartholomew), *288.
Charges for, service, 210.
Men or wrecking crew? (editorial comment), 356.
Luxury or necessity? (editorial comment), 53.
Practice in, work (E. H. Hubert), *27.
Regular vs. night and Sunday rushes (editorial comment), 594.
——Motors and generators, Electric Power Club's recommendations for installation and care of *540, editorial comment, 548.
——Transformers, care and operation of power, *348, editorial comment, 357.
Installation (see motor installation).
Instruments (see Meters).
Insulation
——Armature, 408.
——Dielectric constants for, 313.
International Harvester Company's works, *70.
Iron (see Handling materials).

## L

Ladders for maintenance work, folding, *217.
Lamps (see also Lighting).
——Arc, eliminating noises of, 265.
——Burning out accumulations of explosive gas, for (Dr. H. C. P. Weber), *216.
——Cleaning (N. T. Gordon), *46.
——Gage, moving lamp for reading glass oil (A. J. Dixon), *215.
——Rugged, in mill lighting (James M. Ketch), *58.
——Testing board (Donald L. Hoare), *272.
——Type C Mazda, trouble with, 314.
Lift trucks (see Trucks).
Lighting (see also Lamps).
——Extensionlight, mounting (Philip E. Bernholz), *267.
——Flexibility in a, system (James M. Ketch and A. F. Irish), *251.
——Guesswork vs. investigation (editorial comment), 263.
Lighting:
——Mill, importance of rugged lamps and proper reflectors localized for (James M. Ketch), *58.
——More, for the same money, how we get (editorial comment), 453.
——Needed two hours every day (editorial comment), 105.
——Obsolete system, revamping an (J. J. McLaughlin), *571.
——Regulations, a summing of industrial (G. H. Stickney), *447.
——Shafting, above, helps oiler and inspector (H. M. Cullen), 460.
——Timken Roller Bearing Company's plant (D. P. Hess and Ward Harrison), *485.
Lubrication (see Bearings).

## M

Magnetic "old man," drilling holes on surface of large cylinder with (W. A. Plant), *512.
Magnets, lifting:
——Applications of, various (F. W. Jessop), *419.
——Charging cars for annealing furnace, loads and unloads, *321.
——Iron, for removing stray, *222, (J. H. Gallant), *269.
——Pipe, for handling, *117.
——Plating tank, recovers small iron parts from (H. S. Rich), 315.
——Repairs and doing without, for two months cost more than new one, *369.
——Scrap, for handling, *169.
Magnets, remagnetizing, *54.
Maintenance (see Inspection and maintenance).
Measurements (see Meters).
Meters:
——Graphic (editorial comment), 502.
——Graphic, as a watch dog, *584.
——Voltage at, terminals, *313.
——Watt-hour, reversal of rotation of, 409, *457.
Mills:
——Cotton, good electrical installations in, *20.
——Pulp, pumping system for a sulphite (H. E. Stafford), *489.
——Steel:
Bearings (D. M. Petty), 477.
Electrical development (Walter C. Kennedy), 474.
Foundry electrification (Leonard W. Egan), 483.
Hoists, blast furnace skip (A. C. Cummings and A. R. Leavitt), 484, *513.
Operation, problems in, *474 (editorial comments, 502, 503.
Pumps, motor-operated centrifugal (B. A. Cornwell), 480.
Transportation, electric (F. O. Schnure), 483, *555.
U. S. Steel Corporation's works, *2.
Model shows revolving field of induction motor (Henry Mulford), *462.
Motor bearings (see Bearings).
Motor control:
——Compensator mounted to make repairs easier (J. H. Sauve), *315.
——Controllers:
Car, marked templets for ringing out, after overhauling (J. A. Horton), *606.
Contacts altered for quick renewal (R. Fokes), *461.
Switch relieves, while motor is running (J. H. Sauve), *605.
——Electric Power Clubs' recommendations for *540, (editorial comment), 548.
——New equipment produced in 1922 (E. H. Hubert), *89.
——Rheostats:
Starting trouble caused by changing, 409.
Water, in rotor of pump motor (P. N. E.), *603.
——Slip-rings motor, trouble with equipment for, 601.
——Stopping first of two motors when second stops, automatically (Victor Orth), *59.
——Star-delta connection used to start motor under heavy wad (Earl Baber), *602.
——Starters:
Dust aways from keeping (J. Jensen), *459.
Improvised, for three-phase induction motor (A. J. Dixon), *214.
Mounting, for motors of individually-driven machines (F. W. McGraw), *110.
Mounting, on column (Eustace C. Soares), *363.
Synchronous motor, location of equipment for, 266, 359.
Three-phase operation, changing two-phase for, 108.
——Switch to relieve controller while motor is running, a short-circuiting (J. H. Sauve), *605.
——Switches mounted on one column, two oil (R. S. Huntington), *412.
Motor drive (see Belts, Chains, Couplings, Gears, etc.).
Motor failure:
——Explosion of toally-inclosed motor, 601.
——Oil switch blade causes, loose (H. S. Knowlton), 605.
Motor-generators:
——Connected to render various services (A. W. McAuly), *164.
——Trouble with, 359.
Motor inspection (see Inspection and maintenance and motor repairs).
Motor installation and mounting:
——Electric Power Club's recommendations for, *540, (editorial comment), 548.
——Key installations (editorial comment), 53.
——Small motors (H. S. Knowlton), *591.
Motor maintenance (see Inspection and maintenance and Motor repairs).
Motor mounting (see Motor installation and mounting).
Motor protection (editorial comment), 310.
Motor repairs (see also Tools).
——Alternating-current, reducing speed of, 553.
——Armatures:
Baking and dipping (John S. Dean), *165, *367.
Banding large, putting tension on wire when (Frederick Krug), *320.
Banding machine made from old lathe (H. R. Wass), *607.
Coil-windin' man, the (James Edward Hungerford), 26.
Defects that appear at the brushes, some troubles caused by (E. H. Martindale), *575.
Dipping and baking (John S. Dean), *165, *367.
Motor repairs:
Direct-current, data for old (A. C. Roe), *98.
Handling, iron band as slings for (Frederick Krug), *366.
Insulation, 408.
Testing, growler for, *505.
Winding rack made from pipe and fittings (John W. Hobart), *418.
Winding small, devices for (H. E. Ewalt), *113.
Winding of small motors, testing, *265.
——Brushes shifted by hand, repulsion-induction (Henry Mulford), *316.
——Business side of (editorial comment), 452.
——Coils:
Basket-shape, rewinding motor with, 457.
Double-nose, winder for (E. T. Walk), *366.
Field, fixtures to hold, while being taped (J. M. Walsh), *558.
Grounded field, connection increased motor speed (J. A. Horton), *556.
Induction motor, grouping (A. C. Roe), *137 *197, *241, *293.
Removing, without damaging, 159.
Stator winding, killing, 457.
Winding machines, motor drive for, saves over head belting (J. E. Hcusely), *319.
——Commutator:
Heating, before soldering, iron ring useful for (Frederick Krug), 319.
Sparking at brushes, 264.
——Costs:
Analyzing electrical repair shop (George P. Svendsen), *23.
Job, what is the cost of the (editorial comment) 310.
——Direct-current:
Compound, why does it reverse, 360.
Direction they rotate, importance of knowing, before overhauling (J. A. Horton), 367.
220-volt motor changed for 110-volt, *314.
——Drying out motors (E. C. Soares), *57.
——Equipment and materials for small repair shop. (J. P. Collopy), *167.
——Explosion of totally-inclosed motor, 601.
——Exposed to weather, Lengthening life of motor. (A. C. Roe), 464.
——Fans, rewinding desk, *411
——Fields, changing connections of, *314.
——Four speeds, rewinding for, *212, 551.
——Gregory Electric Company, procedure in (J. D. Zook), *383.
——Horsepower from winding data, figuring, *107.
——Induction—Motor:
Coils, laying out. (A. C. Roe), *137, *197, *241, *293.
Distribution and chord factors in winding stators of (A. M. Dudley), *340.
Four speeds, rewinding for, *600.
Heating of, due to grounded wedges (A. C. Roe), 60.
Model Shows, revolving field of (Henry Mulford), *462.
Three-phase, laying out and checking up diagrams for (A. C. Roe), *491.
Two-and four-speed windings (A. C. Roe), *585.
Two-phase, on three-phase circuit, operating, *551.
Winding diagrams, laying out and checking up (A. C. Roe), *439.
Winding of, changing, 553.
Windings, stubbing and connecting (A. C. Roe), *534.
——Moving motor over an obstacle (Henry Mulford), *508.
——Reconnecting, for half speed, 159.
——Ring, low-resistance end, reduces speed (D. C. McKeehan), *61.
——Rotors;
End-ring rebuilding reduces trouble (Stephen Tillman), *61. Comment (D. A. Blodgett), 219.
Reversing position of, caused motor to heat (A. Hervey), 319.
Soldered without soldering iron, large (J. P. Collopy), *218.
Support facilitates winding, adjustable (Stephen Tillman), *272.
——Single phase.
Rewinding, 506.
Speed of, changing, 361.
——Speed:
Alternating-current, reducing, 553.
Reducing, without changing horsepower (A. C. Roe), 166.
Single-phase, changing, 361.
——Stator:
Coils in winding, killings, 457.
Coils in, what's your best record for inserting (Practical Pete), *471.
Single-phase compensated series motor, winding (A. C. Roe), *416.
——Stripping a motor, data to be taken before (N. S. Davis), *60.
——Two-phase to three-phase, change made by springing coils to different pitch (A. C. Roe), 218.
——Two-phase motors changed to three-phase, 600.
——Three-phase, changing single-phase motor to, 56.
——Three-phase, four-pole, 60 cycle, 36 slot motor with 18-coil basket winding, 57.
——Vibration in motors, eliminating (Freerick Krug), 604.
——Walworth Mfg. Co., industrial plant repair, shop of the, (E. J. Ford), *124.
——Winding:
Data card for a. c. and d. c. machines (V. G. Weber), *416.
Testing, of small motors, *55.
Motor Starters (see Motor control).
Motor testing (see Testing).
Motor troubles (See Motor repairs).
Motors (See also Motor control, Motor installation, Motor repairs, etc.)
——Buying, to use—not to repair (Practical Pete), *519.
——Fluctuating loads, to drive (V. D. Green), *363.
——Good, service is no accident (Practical Pete), *69.
——New, produced in 1922 (E. H. Hubert), *89.
——Temperatures for, operating (O. C. Schoenfeld), 547.
Mounting Motors (See motor installation and mounting).

## N

Nameplates, tinfoil for cleaning (Henry Mulford), 214.
National Biscuit Company's Works, 174.
National Board of Fire Underwriters (See National Electrical Code).
National Electrical Code changes (E. H. Hubert), *187.
National Fire Protection Association (See National Electrical Code).
National Safety Council:
——Congress, program of, *454.
New Products produced in 1922 (E. H. Hubert), *89.
1922, review of new products produced in (E. H. Hubert), *89.

## O

Oiling (See Bearings).

## P

Packingtown, Union Stock Yards, Chicago, *228.
Paper (See Handling materials).
Pillsbury Flour Mills Company's Works, *122.
Pinions, use of (G. A. Van Brunt), *81.
Pipes, electrically-thawing frozen water (Dexter W. Allis), *161, comment (G. H. McKelway), 267.
Plating:
——Generator sparks, what to do and what not to do when (H. S. Rich), 268.
——Magnet recovers small iron parts from tank (H. S. Rich), 315.
Power factor:
——Correcting, calculating generator capacity for use as condenser for (R. W. Lloyd), *163.
——Determining, graphic method of (W. L. Stevens), *318.
Power transmission (See Belts, Chains, Couplings, Gears, etc.).
Practical Pete (See Index of authors).
Production control, the dark horse in (editorial comment), 262.
Protection (See Fuses).
Pulleys:
——Guard keeps oil which escapes from bearing from saturating belt (A. J. Dixon), *110.
——Removing solid rim, from shafting (A. J. Dixon), *267.
——Size, for motor, 158.
——Tight, moved on its shaft (A. J. Dixon), *270.
Pullman Company's Works, *472.
Pulp Mills (See Mills).
Pumps:
——Centrifugal, in steel industry, motor-operated (B. A. Cornwall), 480.
——Cylinder, forcing new lining in (James P. Marshall), *113.
——Impeller causes motor overload, oversize (Eustace C. Soares), 318.
——Signal lamp lights up when pump accidentally stops (F. G. Bonn), *509.
——Sulphite pulp mill system for (H. E. Stafford), *489.
——Water, cost of pumping (editorial comment), 548.
Purchasing methods (editorial comment), 104.

## Q

Questions and answers, *54, *106, *158, *210, *264, *312, *358, *408, *455, *504, *550, *597.

## R

Records:
——Auditing procedure in maintenance work (Arthur J. Whitcomb), *11, *426.
——Belt operator (E. D. F.), *556.
——Cards give complete record of electrical equipment (W. R. Gibson), *367.
——Diagrams, laying out and checking up three-phase (A. C. Roe), *491.
——Motor data card (E. J. Ford), *463.
——Motor installations, forms for (Edwin S. Wagner), *438.
——Stripping motor, data to be taken before (N. S. Davis), *60.
——System in electrical division work (P. T. Vanderwaart), *482.
——Transfer cards for equipment keep records up-to-date (D. Fliegelman), *320.
——Winding data card for ac. and d.c. machines (V. G. Weber), *416.
——Winding diagrams, laying out and checking up (A. C. Roe), *439.
Reflectors:
——Cleaning (N. T. Gordon), *46.
——Localized in mill lighting (James M. Ketch), *58.
——RLM standard dome, *108, correction, 160.
Repairs (See Generator and Motor repairs).
Rewinding (See Motor Repairs).
Ring-fire (R. Tokea), 162.
Rotors (See Motor Repairs).

## S

Safety:
——Accident prevention is cheap production insurance (editorial comment), 407.
——Accident, 29 months without a lost-time (Wilbur Woodams), *37.
——Foreman's part in safety work, the (editorial comment), 452.
——National Safety Council's Congress, program of, *454.
——Switches; what are the requirements of protection that safety switches can provide? (D. H. Braymer), *389.
Sawmill Machinery, power required in operation of (F. G. Bonn), 162.
Screwdriver (See Tools).
Service around the works (editorial comment), 311.
Shaft repairing in an emergency (A. J. Dixon), *458.
Sign, take a look at your roof (Practical Pete), 431.
Signals:
——Direct-current control, low-voltage (Paul F. Clausen) *257.
——Grounded circuit, for (P. Whalen), *164.
Signals:
——Loads ready or empty trailers wanted, notifies move men of, 274.
——Pump accidentally stops, lamp indicates when (A. J. Dixon), * 57, (F. G. Bonn), *509.
——Valve on tank has opened, lamp indicator shows which air-operated (W. W. Peasgood), *412.
——Water tank, using a float on high and low-water alarm for (A. J. Dixon), *316.
Skids protect delicate machined parts in handling, *170.
Society of Industrial Engineers' Convention (Frank E. Gooding), 276.
Soldering irons, electric furnace for heating (A. S. Barker), *464.
Speed reducers, information about (G. A. Van Brunt), *131.
Staging for work on overhead equipment, portable (L. B. C.), *362.
Standard Oil Company's works, *280.
Standards, electric power apparatus (editorial comment), 595.
Starters (See Motor Control).
Stators (See Motor Repairs).
Steel Corporation's works, U. S., *2.
Steel Mills (See Mills).
Steinmetz, Charles Proteus, death of *596.
Storage batteries (See Batteries).
Studebaker Corporation of America, works of, *328.
Substation, remodeling an industrial (Eustace C. Soares), *545.
Switchboard simplifies testing motors by the pump-back method (Eustace C. Soares), *557.
Switches:
——Frame for supporting, upright conduits used as (R. S. Huntington), *458.
——Knife-blade, good service evidence for (Practical Pete), *327.
——Oil, two mounted on one column (R. S. Huntington), *412.
——Safety:
Ice-plant service, in (Practical Pete), *423.
Installations, two good clean-out (Practical Pete), *121.
Manufacturer furnishes as a, what the, 398.
Requirements of protection from, what are (D. H. Braymer), *389.
User expects of, what the, 395.

## T

Tape more easily handled, making rolls of (S. H. Samuels), *607.
Telephone instruments, design of, 119.
Terminals made from copper tubing in emergency (Harry S. Rush), *558.
Testing:
——Armatures, growler for, *505.
——Coils, motor field, *159, 210.
——Fuses:
Board for (Donald L. Hoare), *272.
Tester made from pocket flashlight (J. E. McCarthy), *219.
——Lamps:
Board for (Donald L. Hoare), *272.
550-volt a.c. circuits, for (J. H. Sauve), *416.
——Load, on direct-current motors (J. M. Walsh), *111.
——Motors:
Alternating-current (J. Elmer Housley), *331, comment (C. H. Funderberg), 375.
Coils, field, *159, 210.
Driving fluctuating loads (V. D. Green), *363.
Switchboard simplifies, by the pump-back method (Eustace C. Soares), *557.
Transformer for high-voltage, on small motors (A. C. Roe), *559.
——Resistance, portable outfit with simple grid connections to give wide range of (Eustace C. Soares), *62.
——Windings of small motors, *55, *265.
Thawing fronzen water pipes by electricity (Dexter W. Allis), *161, comment (G. H. McKelway), 267.
Tiering machine (See Elevators).
Tier-lift trucks (See Trucks).
Tools:
——File lessens work of reaming small holes, motor-driven (G. A. Luers), *607.
——Hacksaw blades, made from old (Nelson Hall), *273.
——Home-made (editorial comment), 209.
——Jointing, for heavy wire (G. A. Luers), *554.
——Motor repairman, easily made, for (J. H. Gallant), *272.
——Screwdriver for assembling small parts, hand-whittled wooden (Henry Mulford), 115.
——Simple, for repair shops (E. J. Ford), *165.
——Vise to hold large parts, angle-iron extensions enable, *271.
——Washer cutter for bench use (G. A. Luers), *511.
Tractors:
——Coal pile, improvised drag line made from scraper and tractor for leveling (H. S. Rich), *466.
——Screw machine turnings, for handling loose, *116.
——Tracks may be moved by, or by hand, *274.
Trade literature, 68, 120, 172, 226, 278, 325, 374, 421, 470, 518, 565, 614.
Trailers (See also Trucks):
——Coupling, into a train for industrial haulage, *221.
——Wearing out concrete floors, preventing, 221.
Transformers:
——Care and operation of power, *348, editorial comment, 357.
——Neutral and ground, voltage between, 409.
——1 to 1-ratio, winding a, *313.
——Series, sectional short circuit caused burn-out of entire coil in (Henry Mulford), 270.
——Substation, remodeling on industrial (Eustace C. Soares), *545.
——Tests on small motors, for high-voltage (A. C. Roe), *559.
——Troubles—some symptoms of, their diagnosis and remedies (H. E. Stafford), *402.
——Voltage from, connected in different ways, *599.
Transportation (See Handling materials, Tractors, Trucks, etc.)
Transmission of power (see Belts, Chains, Couplings, Gears, etc.)
Trucks, electric:
——Cores in steel foundry, handling, 170.
——High-wheel, for inside haulage and street use, *560
Trucks, electric:
——Lift:
Cottonseed oil meal, for bags of, *370.
Dies, for handling, *116.
Motor plant, in, *609.
Paper rolls, for handling, *64.
Picks up and supports load on extending fingers, *561.
——Platforms protected from heat of hot forgings by special box skid, *275.
——Tier-lift (See Trucks, Lift).
Trucks, non-electric:
——Castings between machines, handling, *561.
——Dies, stamping, for handling, *465.
——Hand or tractor, may be moved by, *274.

## U

U. S. Stee lCorporation works, *2.

## V

Vaporizer, electric (Albert Kochs), *415.
Vehicles (See Tractors, Trailers and Trucks).
Vise to hold large parts, angle-iron extensions enable (G. A. Luers), *271.

## W

Walworth Mfg. Company's repair shop (E. J. Ford), *124.
Waste, dividends from eliminating (editorial comment 104.
Wasted time (editorial comment), 262.
Welding, Arc:
Connector for leads, bayonet-type (R. H. Davis), *412.
——Flasks in foundry, cuts repair costs on worn (A. M. Candy), *511.
——Rods for, composition of hard-drawn (D. N. Louis) 61.
Winding (See Motor repairs).
Wire (See also Wiring):
——Enameled, invention and development of (Charles R. Underhill), 607.
——Enameled, removing insulation from, 505.
——Hose protects wires in conduit from water, rubber (F. G. F.), *268.
——Jointing tool for heavy (G. A. Luers), *554.
——Lead-covered, where they are necessary in industria plants (F. A. Westerbrook), 215.
——Motor leads and jumpers, for a.c. (A. C. Roe), 115
Wiring (see also Wire):
——Conduiet in wiring for motor, choosing proper. (C. Dickerson), 59.
——Motor lead grounded to conduit shunts out a meter. (Allan H. Cunha), *415.
——Panel board, connecting lights and small motors to the same, 455.
——Power, in California laundry, (Practical Pete), *279.
——Stairway, four-story building, *211).
——Temporary installations, beware of (editorial comment), 595.
——Trouble in circuit, locating, *410, 505.


*Indicates illustrated articles

## INDEX OF AUTHORS


ALLIS, DEXTER W. Thawing frozen water pipes by electricity, *161, comment (G. H. McKelway), 267.
Arny, Louis W. Making laps for cemented endless leather belts, *265.
——Making endless leather belts for transmission purposes, *413.
——Leather cement and how to apply it in joining leather belts, 459.

BABER, EARL. Star-delta connection to start motor under heavy load, *602.
Barker, A. S. Electric furnace for heating soldering irons *464.
Bartholomew, G. W. How to figure rates for industria maintenance service, *288.
Beecher, R. M. Obtainig a.c. from d.c. machine, *602.
Bernholz, Philip. Exploring coils simplify work of tracing conductors, *271.
——Mounting an extension light, *267.
——Obtaining a.c. from d.c. machine, *413.
Blodgett, D. A. Rebuilding rotor end-rings to reduce trouble, 219.
Bonn, F. G. Determination of power required in the operation of sawmill machinery, 162.
——Signal lamp indicates when pump accidentally stops, *509.
Braymer, Daniel H. Duties and responsibilities of the engineer and electrical contractor, *16.
——Requirements of protection that safety switches can provide, *389.

CANDY, A. M. Arc welding cuts repair costs on worn flasks in foundry, *511.
——Speed of cutting cast iron of various thickness by electric arc, *220.
Clausen, Paul F. Low-voltage d.c. control, *257.
Collopy, J. P. Equipment and materials needed for small repair shop, *167.
——Soldering large rotor without use of soldering iron, *218.
Cornwell, B. A. Motor-operated centrifugal pumps, 480.
Cullen, H. M. Light above shafting helps oiler and inspector, 460.
Cunha, Allan H. Motor lead grounded to conduit shunts out a meter, *415.
Cummins, A. C., and A. R. Leavitt. Blast furnace skip hoists, 484, *513.

DAVIS, N. S. Date to be taken before stripping motor, *60.
Davis, R. H. Bayonet-type connector for welding leads, *412.
Dean, John S. Dipping and baking armatures, *165.
——Dipping and baking rewound armatures, *367.
Dickerson, C. Choosing proper type condulet when wiring for motor, 59.
Dixon, A. J. Arranging laps of cemented joints in belts, *362.
——Improvised starter for a three-phase induction motor prevented a shut-down, *214.
——Moving lamp helps in reading glass oil gauge, *215.
——Moving tight pulley on its shaft, *270.
——Pulley guard keeps oil which escapes from bearing from saturating belt, *110.
——Reclaiming a seemingly wornout emery-wheel arbor, *463.
——Removing solid rim pulley from shafting, *267.
——Repairing driveshaft in emergency, *458.
——Signal lamp indicates when pump accidentally stops, *57.
——Using a float on high and low-water alarm for water tank, *316.
Dudley, A. M. Distribution and chord factors in winding stators of induction motors, *340.

EGAN, LEONARD W. Electrification of the foundry, 483.
Ewalt, H. E. Devices for winding small armatures, *113.

FALTER, P. H. Electric steam boilers, *403, comment (W. A. Plant), 509. Answer (P. H. Falter), 509.
Fliegelman, D. Transfer cards for equipment keep records up-to date, *322.
Fokes, R. Altering controller contracts for quick renewal, *461.
Ford, E. J. Industrial plant repair shop, *124.
——Motor record card, *463.
——Simple tool for repair shop, *165.
Frank, A. A. Bonus on operation and maintenance, *4, correction, 119.

GALLANT, J. H. Easily made tools for the motor repairman, *272.
——Magnet to remove stray iron from coal, *269.
Gibson, W. R. Cards give complete record of electrical equipment, *367.
Gooding, Frank E. Better methods of handling materials, *41.
——Chain drives reduce production losses, *432, editorial comment, 453.
——Fabric-base and leather belts, *147.
——Installation and operation of flexible couplings, *579.
——Operating conditions affecting belt service, *189 correction (R. H. Whitney), 324.
——Operating conditions affecting chain service, *379.
——Reclaiming leather belts, *304, editorial comment, 311.
——Report of Cincinnati meeting of Society of Industrial Engineers, 276.
——Servicing industrial belts, *236, editorial comment, 262.
——Types and kinds of chain drives, *335, editorial comment, 357.
——Types and kinds of flexible couplings, *529, editorial comment, 548.
——Use of rigid and compression couplings, *499.
Gordon, N. T. Cleaning lamps and reflectors, *46.
Green, V. D. Tests on use of special motors to drive fluctuating loads, *363.

HALL, NELSON. Useful tools made from old hacksaw blades, 273.
Hanlon, George Wm. Finding proper position of brushes on commutator, *554.
Hantman, B. Operating and maintenance practice for electric traveling cranes, *176.
Harazim, Frank. Making anchor bolts adjustable, *458.
Harrison, Ward, and D. P. Hess. Relation of lighting to production in Timken Roller Bearing Company's plant, *485.
Hervey, A. Reversing position of rotor caused motor to heat, 319.
Hess, D. P. and Ward Harrison. Relation of lighting to production in Timken Roller Bearing Company's plant, 485.
Hobart, John W. Armature-winding rack made from pipe and fittings, *418.
Hoare, Donald L. Inexpensive board for testing lamps and fuses, *272.
——Restoring service quickly after fuse blows, *605.
Horton, J. A. Grounded field coil connection increased motor speed, *556.
——Importance of knowing direction d.c. motors rotate before overhauling, 367.
——Marked templets for ringing out car controllers after overhauling, *606.
Housley, J. Elmer. Making motor tests, *331, comment (C. H. Funderberg), 375.
——Motor drive for coil winders saves overhead belting, *319.
——Graphic meter as a watch dog, *584.
Howard, E. R. Stove bolts and pieces of lead pipe used for anchor bolts, *214.
Hubert, E. H. Changes in National Electrical Code, *187.
——Practice in maintenance work, *27.
——Review of new products produced in 1922, *89.
Humphrey, Joseph B. Care in oiling bearings, 161.
Hungerford, James Edward. The coil—windin' man, 26.
Huntington, R. S. Mounting two control switches on one column, *412.
——Upright conduits used as frame for supporting switches, *458.

IRISH, A. F. and James M. Ketch. Flexibility in a lighting system, *251.

JENSEN, J. Keeping dust away from motor starting equipment, *459.
Jessop, F. W. Applications of lifting magnets, *419.

KENNEDY, WALTER C. Electrical development committee of A. I. S. E. E., report of, 474.
Ketch, James M. Importance of rugged lamps and proper reflectors localized in mill lighting, *58.
Ketch, James M., and A. F. Irish. Flexibility in a lighting system, *251.
Knowlton, H. S. Results of thorough inspections, *231.
——Motor failures caused by loose oil-switch blade, 605.
——Mounting small motors, *591.
Kochs, Albert. Electrically-heated tank for vaporizing water, *415.
——Flat-topped electric heater for contact drying, *268.
Krug, Frederick. Inexpensive flexible coupling for special job, *315.
——Eliminating vibration in electric motors, 604.
——Iron band as sling for handling armatures, *366.
——Iron ring for heating commutator before soldering, 319.
——Oil leaks in bearings, 605.
——Putting tension on wire when bandings large armatures, *320.

LEAVITT, A. R. and A. C. Cummins. Blast furnace skip hoists, 484, *513.
Lincoln, E. S. Preventing shutdowns in Bossert Corporation's plant, *283.
Lloyd, R. W. Calculating generator capacity for use as condenser to correct power factor, *163.
Louis, D. N. Composition of hard-drawn rods for arc-welding, 61.
Luers, G. A. Angle-iron extensions enable vise to hold large parts, *271.
——Easily-made clip for emergency connections, *461.
——Holder for desk memorandum roll paper, *510.
——Inexpensive counterweights, *508.
——Jointing tool for heavy wire, *554.
——Motor-driven file lessens work of reaming small holes, *607.
——Washer cutter for use at bench, *511.

MARSHALL, JAMES P. Forcing new lining in pump cylinder, *113.
Martindale, E. H. Defects in a commutator, *153.
——Troubles caused by armature and field defects that appear at the brushes, *575.
McAuly, A. W. Motor-generator set connected to render various services, *164.
McCarthy, J. E. Fuse tester made from pocket flashlight, 219.
McGraw, F. W. Mounting starters for motors of individually-driven machines, *110.
McKeehan, D. C. Low-resistance end ring reduces motor speed, *61.
McKelway, G. H. Thawing frozen water pipes by electricity, 267.
McLaughlin, J. J. Revamping an obsolete lighting system, *571.
Moore, Edward T. Electric furnace phenomena, 483.
Mulford, Henry. Better service from flashlight cells by cleaning contacts, 110.
——Hand-whittled wooden screwdriver for assembling small parts, 115.
——Heating of ferrule-type fuses in single finger clips, 317.
——Improvised crane to take high-pressure cylinder from large engine, *460.
——Model to show revolving field of induction motor, *462.
——Moving a motor over an obstacle, *508.
——Sectional short circuit caused burn-out of entire coil in series transformer, 270.
——Tinfoil can be used for cleaning nameplates, 214.
——To maintain service brushes on repulsion—induction motor shifted by hand, *316.

ORTH, VICTOR. Automatically stopping first of two motors when second stops, *59.

PEASGOOD, W. W. Lamp indicator shows which air-operated valve on tank has opened, *412.
——Safeguard to keep hoist from overrunning by stopping motor, *415.
Petty, D. M. Report of special bearng committee of A. I. S. E. E., 477.
Plant, W. A. Drilling holes on surface of large cylinder with magnetic "old man," *512.
——Operation of electric steam boilers, 509.
Practical Pete. Awel, it's aboot so, *227.
——Brushes with 20-year service record, *173.
——Buying motors to use—not to repair, 519.
——Good motor service is no accident, *69.
——Here is some good service evidence, *327.
——How they do it in California, *279.
——It's 25 days 'till Christmas, *567.
——Jerk up the handle and out comes the ice, *423.
——Take a look at your roof sign, 431.
——The coil windin' man, 26.
——This certificate of appreciation, *1.
——Thorough testing saves future worries, *375, editorial comment, 453.
——Two good clean-cut installations, *121.
——What's your best record for inserting coils in a stator? *471.

RAMBOUSEK, W. L. Hook facilitates overhead installation of cable in factory building, *215.
Rich, H. S. Improvised drag line made from scraper and tractor for leveling coal pile, *466.
——Magnet recovers small iron parts from plating tank, 315.
——Sparking of plating generator, 268.
Roe, A. C. Alternating current fans burn out when six blades are substituted for four, 219.
——Connecting data for some old d.c. armatures, *98.
——Connecting induction motors, *137.
——Heating of induction motor due to grounded wedges, 60.
——How to group coils, *197.
——Laying out unequal groupings of coils in induction motors having from four to forty-eight coils, two or three-phase, *241.
——Laying out unequal groupings of coils in induction motors having from twenty to twenty-four poles, two and three-phase, *293.
——Laying out and checking up winding diagrams for lap-wound induction motors, *439.
——Laying out and checking up three-phase diagrams, *491.
——Lengthening life of motor exposed to weather, 464.
——Motor changed from two-phase to three-phase by springing coils to different pitch, 218.
——Motor speed reduced without changing horsepower, 166.
——Size of wire for a.c. motor leads and jumpers, 115.
——Stubbing and connecting windings of induction motors, *534.
——Transformer for high-voltage tests on small motors, *559.
——Two-and four-speed windings, *585.
——Winding stator of single-phase compensated series motor, *416.
Rush, Harry S. Terminals made from copper tubing in emergency, *558.

SAMUELS, S. H. Making rolls of cotton tape more easily handled, *606.
Sauve, J. H. Mounting compensator to make repairs easier, *315.
——Short-circuiting switch to relieve controller while motor is running, *605.
——Testing lamp for use on 550-volt a.c. circuits, *416.
Schnure, F. O. Electric transportation in steel plants, 483, *555.
Schoenfeld, O. C. Operating temperatures for electric motors, 547.
Seward, William E. Fuse protection for motors, *85.
Soares, Eustace C. Drying out motors, *57.
——Motor overloaded by over-size impeller in pump, 318.
——Mounting starting equipment for motor on column, *363.
——Portable outfit with simple grid connections to give wide range of resistance, *62.
——Remodeling of an industrial substation, *545.
——Switchboard which simplifies testing motors by the pump-back method, *557.
Stafford, H. E. Pumping system for a sulphite pulp mill, *489.
——Symptons of transformer troubles— their diagnosis and remedies, 402.
Stevens, W. L. Graphic method of determining power factor, *318.
Stickney, G. H. Industrial lighting regulations, *447.
Svendsen, George P. Analyzing electrical repair shop costs, *23.

TILLMAN, STEPHEN. Adjustable support for rotors facilitates winding, *273.
——Rebuilding rotor end-rings reduces trouble, *61 comment (D. A. Blodgett), 219.
Tokea, R. Ring-fire, 161.

UNDERHILL, Charles R. Invention and development of enameled wire, 607.

VAN BRUNT, G. A. Gears and speed reducers *131.
——Maintenance analyses and procedure, *48.
——Material-handling scheme in Bates Expanded Steel Truss Company's works, *345.
——Use of gears and pinions, *81.
Vanderwaart, P. T. System in electrical division work, *482.

WAGNER, EDWIN S. Record forms for motor installations, *438.
Walk, E. T. Coil-winder for making double-nose coils *366.
Walsh, J. M. Electric elevator inspection, *72.
——Fixtures to hold field coils while being taped, *558.
——Making a load test on direct-current motors, *111.
Wass, H. R. Armature banding machine made from old lathe, *607.
Weber, Dr. H. C. P. Burning out accumulations of explosive gas by a special lamp, *216.
Weber, V. G. Complete winding data card for a.c. and d.c. machines, *416.
Westbrook, F. A. Trouble avoided by use of special oil-proof cable on machines, *364.
——Where lead-covered conductors are necessary in industrial plants, 215.
Whalen, P. Alarm given when circuit is grounded, *164.
Whitcomb, Arthur J. Auditing procedure in maintenance work, *11.
——Checking and distributing power costs, *181, editorial comment, 208.
——Procedure in maintenance can be audited, *426.
Whitney, R. H. Operating conditions affecting belt service, 324.
Woodams, Wilbur. Twenty-nine months without a lost-time accident, *37.
Wyatt, James H. Circuit breakers for d.c. motors, *523.

ZOOK, J. D. Repairing and rebuilding electrical equipment, *383.